



## Technical Service Bulletin – 017

### ***HELM Rebound range (number of clicks on Low Speed Rebound Adjuster)***

Rev01 – 5/17/17 - Mike M

File location: \\Bluetail\Engineering\Technical Service Bulletins

File Name: TSB017

Revision	Description	Author	Date
01	First Release	MMc	5/17/17

#### Overview

In early April of 2017 Cane Creek made a change to the rebound portion of the damper. The change was made to the internal push rod that opens and closes the low speed rebound needle when the adjuster is turned. The old push rod was a hollow tube cut to size and the new push rod is a machined bar allowing for zero deflection and greater strength.

The new push rod is longer which changes the number of rebound clicks. Before this change, the adjuster had 14 clicks. After the change, the adjuster has 10 clicks.

This change will not affect the range of rebound damping force.

#### Scope

All Helm forks built after April 18 2017 will have this change.

#### Solution

No service to the rebound is needed.