



Technical Service Bulletin – 026

Helm AIR/COIL Fork – Bladder change

Rev02 – 9/21/18 - Mike M

File location: \\Bluetail\Engineering\Technical Service Bulletins

File Name: TSB026

Revision	Description	Author	Date
01	First Release	MMc	8/13/18
02	Added picture of bladder showing “H” symbol identifying newest Generation.	MMc	9/21/18

Overview

In August of 2018 Cane Creek made a change to the Helm damper bladder. We changed material in the bladder to HNBR to be more resilient.

Scope

This change is for all new product released after August 5, 2018.

Solution

No solution needed. Current bladders in the field only need to be changed at the 100hr damper service interval.



“H” embossed in bladder
designating material change.

Old Stock will not have “H”