



## Technical Service Bulletin – 014

### ***DB AIR air seal head quad ring***

***Old:AAD1163 New:AAD1847***

Rev01 – 4/18/17 - Mike M

File location: \\Bluetail\Engineering\Technical Service Bulletins

File Name: TSB014

Revision	Description	Author	Date
01	First Release	MMc	4/18/17

### Overview


It was discovered that a small batch of new DB AIR; air seal head quad rings (AAD1163) have defects such as cuts and impressions to the inner surface.

### Scope

This issue affects a small number of DB AIR shocks built in 2017.

### Solution

All product at Cane Creek has been confirmed to be acceptable for use. Any shocks built after 4/18/17 with Blue Quad rings are confirmed ok. Shocks built before this date are suspect to replacement of the air seal head quad ring. Cane Creek will switch to the black quad rings once all of the remaining blue quad rings have been exhausted from stock.



Defect examples