

Technical Service Bulletin - TSB048

Kitsuma Oil Seal Head Torque Value

Rev01 - 02/01/2022

File location: C:\CaneCreek-PDM\Engineering Documents\Technical Service Bulletins\TSB - Rear

Suspension

File Naming: TSB048

| Revision | Description | Author | Date |
|----------|---------------|--------|-----------|
| 01 | First Release | JYJ | 5/30/2023 |

Overview

Air Oil Seal Head (ACD0122) and Coil Oil Seal Head (ACD0121) should be Torqued to 22 Nm, previously torque was 15Nm. This will aid in preventing OSH from backing out

Scope

All Kistuma air and Kitsuma Coil Products built or serviced after 5/30/2023 should be toque to 22Nm

Solution

Air Oil Seal Head (ACD0122) and Coil Oil Seal Head (ACD0121) will be Torqued to 22 Nm